

VERSION REPORT

PRODUCT:

DDS VERSION V08.18

03/08/2017

CONTENTS

1	Checksum	2
1.1	Checksum DDS V08.18.....	2
2	Manuals.....	2
3	Product stop	2
4	Incompatibilities.....	2
4.1	Hardware.....	2
4.2	Software	2
5	Hardware modifications	2
6	New features	2
6.1	Allows the complete management of the new Flashes.	2
6.2	Recognizes a new version "2" of MAB PLDs	2
7	Modifications	2

1 CHECKSUM

1.1 CHECKSUM DDS V08.18

Location	Identifier
\\fas\Soft_interno\Reg\DDS-SETUP+LOAD-DDS\V-estándar\V0818WIN.exe	4612

2 MANUALS

No changes.

3 PRODUCT STOP

It does not correspond to any product stop.

4 INCOMPATIBILITIES

4.1 HARDWARE

None.

4.2 SOFTWARE

The WinDDS that supports the V8.18 allows the recording of any drive version, in both the old and new Flashes. However, the use of WinDDS prior to this one to record any version, including V8.18, on the new Flashes, produces a TIMEOUT error before finishing the process.

On the other hand, it has "*" .mot" motor file V2.09, which was already validated in version V08.17.

5 HARDWARE MODIFICATIONS

None.

6 NEW FEATURES

6.1 ALLOWS THE COMPLETE MANAGEMENT OF THE NEW FLASHES.

6.2 RECOGNIZES A NEW VERSION "2" OF MAB PLDS

7 MODIFICATIONS

None.

CORRECTED ERRORS

None.